

URGENT SAFETY NOTICE

We have recently identified a potential quality issue with certain Belling gas hobs installed in holiday homes and caravans manufactured after May 2019.

This is a serious issue which could pose a risk to health, or even death.

Safety is our highest priority. We would ask that all potential owners do the following:

1. Isolate the gas supply to the hob or caravan / holiday home
2. Contact us to arrange a free of charge modification via:
 - a. Email: contactus@belling.co.uk
 - b. Tel: 0343 212 1088

It is vital that all Belling gas hobs detailed below, installed in a holiday caravan manufactured after May 2019, are urgently inspected and modified. This will be conducted free of charge.

Until the modification is completed by a registered Gas Safe engineer, the gas supply to the hob **MUST** be isolated. Once the simple modification is completed, the hob will be safe to use.

If you own one of the affected hobs, or have any concerns, please contact us via email on contactus@belling.co.uk or by telephone on 0343 212 1088.

The affected models are:

444410131	BEL GHU602GC Sta
444410132	BEL GTG60C Blk
444410133	BEL GHU75C Sta
444410134	BEL GTG75C Blk
444410193	ST GTG60C Blk
444410443	BEL GHU602C LPG Sta
444410444	BEL GTG600C LPG Blk
444410446	BEL GHU75C LPG Sta
444410447	BEL GTG75C LPG Blk
444411638	BEL GHU753RI STA

Belling accords the highest priority to safety, and it is vitally important that consumers do not use their gas hob. They MUST isolate the gas supply immediately, by turning off the isolation valve to the hob, or to the holiday home or caravan.